

TRABAJOS REALIZADOS DURANTE EL MES DE JULIO 2019

	Generadas	Terminadas	Pendientes	Eficiencia	Retrazadas	Resueltas	Eficiencia
FACTIBILIDAD	31	31	0	100	0	31	100
INSPECCION	30	28	2	93.33	4	32	106.67
INSTALACION DE DRENAJE	8	6	2	75	2	8	100
INSTALACION DE MEDIDOR	24	14	10	58.33	4	18	75
INSTALACION DE TOMA DE AGUA	23	3	20	13.04	5	8	34.78
RECONEXION DE TOMA	50	44	6	88	7	51	102
REPARACION	21	17	4	80.95	4	21	100
REPORTE DE FUGA	36	32	4	88.89	4	36	100
SUSPENSION DE TOMA	56	21	35	37.5	62	83	148.21
T O T A L E S ...	279	196	83		92	288	